



TECHNICAL BULLETIN

TB0025

4 / 19 / 04

Removal of Overflow Holes

This is a notice that our models 222, 223, 224, 245, 246, 247, & 248 Self Rimming Lavatories will have the overflow holes removed on a go forward basis. This transition of product will happen gradually as older inventory is used up and new inventory is fabricated. These models still meet ANSI & CSA code. This being said, these products could conceivably be unacceptable for some local building codes. Please remember to check these building codes before installation in various locales'.